



BMW SERIE 4 GRAN COUPE

Gran Coupé 420i 184 ch BVA8 M Sport

VIN NO WBA4H31040BM44526

Registration Number EX334NE



MOT Date



Last Service



Number of Owners



Last Service Mileage



Number of Keys



First Registration Date



2018-05-24

Odometer Reading



101317 km

Country First Registered



Inspection Report Summary

Customer	BCAuto Encheres	Report Number	P20251110145937
Inspection Date / Place	2025-11-10 / BCA NANTES	Cosmetic Grade	1


Vehicle Summary

Vehicle Condition	Runner	VAT Type	Exempt Rate
Fuel Type	Petrol	Gearbox Type	Automatic
Colour	Black	Engine Size (cc)	1998
Engine Size	2.0	No of Doors	4
Body Type	Hatchback	Drive Train	Rear
Seat Colour		No of Seats	5
Charging Cables		NEDC CO2 Rating (q/km)	134
Engine Rating CV	10	Metalic Colour	Yes
Accident Damage	No	Euro Emission	

Vehicle History & Documents

Service Book Available	Present	Next Service Mileage	km
Previous Usage	Normal Use	Imported	No
Manufacturer Warrenty			





Equipment

Central locking	Electrically folding wing mirrors	Rear parking sensors	Electric Tailgate
Cruise control	Front parking sensors	Satellite navigation	Electrically adjustable seats
Radio	Alloys wheels	Stability control	Front fog lamps

Power assisted steering

Equipment Details


Presence Anti-Theft Lock Nut	No	Seat Heating	Front
Air Conditioning	Yes	Sunroof Type	Tilt/Slide Steel

Wheels & Tyres


Left Rear Tyre Depth	7	Left Front Tyre Depth	7
Right Rear Tyre Depth	7	Right Front Tyre Depth	7

Cosmetic Damage

7 Dommages



0 Dommages



Component		Damage	Comments
1	Door / Front Left	Paint / Stone Chip	
2	Fender / Front Right	Paint / Scratch / Line	
3	Bumper / Front	Paint / Scratch / Line	
4	Bumper / Back	Paint / Scratch / Line	
5	Door / Front Right	Paint / Scratch / Line	
6	Door / Front Right	Paint / Chipping	
7	Door / Back Right	Paint / Chipping	



1. Door / Front Left
Paint / Stone Chip -




2. Fender / Front Right
Paint / Scratch / Line -




3. Bumper / Front
Paint / Scratch / Line -



4. Bumper / Back
Paint / Scratch / Line -



5. Door / Front Right
Paint / Scratch / Line -



6. Door / Front Right
Paint / Chipping -



7. Door / Back Right
Paint / Chipping -

Mechanical Condition

Levels			
Level - Oil	Not available	Coolant Fluid - Condition	✓
Oil - Condition	NA	Brakes Fluid	✓
Coolant Fluid	✓		
Engine			
Cross Member	✓	Serpentine Belt	✓
Control Liquid Leak	✓		
Equipments Test			
Dump / Trail / Tail Gate Lift	NA	Electric Windows	✓
Convertible, Sunroof, Wagon, Flatbed truck, Tailgate electrics test	✓	Parking Sensors / Cameras Functioning	✓
Main & Spare Keys Functioning	!	Central Locking	✓
Audio Equipment	✓	Navigation System	✓
AC / Heating System	✓		
Dashboard Lights			
ABS Warning Light	✓	Diesel Particulate Filter Light	NA
ESP Fault/Traction Control Malfunction Light	✓	4WD Light	NA
Service Light	✓	Dashboard Working	✓
Engine Light	✓	Oil Pressure Warning Light	✓
Airbag Warning Light	✓	Brake Warning Light	✓
Level - Fuel / Battery	2	Transmission Warning Light	✓
Steering Fluid Level	✓		
Hybrid/EV			
Charge Port Condition	NA	Charge lead 1 condition /Charge lead 2 condition	NA
Hybrid System Fault	NA		
Comments			

Test Drive Inspection

Test Drive			
Engine functioning	✓	Engine / Aux Belt / Pulley Noise	✓
Steering Noise/Gripping	✓	Vehicle Starts	✓
Engine Power	✓	Smoke Quantity	✓
Transmission	✓	Clutch Functioning	✓
Steering	✓	Brakes Functionning	✓
✓ No troubles detected, good condition or correct tests, according to vehicle age and mileage			
! Damages or malfunction detected that requires repairs by the buyer			
NA Not applicable			
☐ Not tested			

Disclaimer Section

The test drive is done on a flat surface and lasts about 2 minutes. The driven distance is a minimum of 300 meters, including a u-turn, an acceleration and a braking phase. The highest speed achieved during this test is 50km/h. The mechanical check is a visual and dynamic diagnosis without any disassembly. We cannot guarantee any mechanical wear part.